


HOPE UNIVERSITY COLLEGE
ADDIS ABABA
ETHIOPIA



PROGRESS REPORT

Project : Construction of Hope University College
To : Dr. Minas Hiruy, Building Consortium (Holland), Ethiopiaid UK, Menlo Park (USA), Ethiopiaid Ireland
Date : 3 December 2008
Prepared by : Niek Hoffius



Service Centre (A) & Classroom Building (B)



The excavation for the foundation of the corridor between the Service Centre at the left and the Classroom Building at the right has begun. The mobile crane in the foreground is casting the concrete for the roof of the library. In the picture at the left, workers are busy fabricating the window frames.

De ontgraving voor de fundering van de corridor tussen het Service Centre links en het Classroom Building rechts is gestart. De mobiele kraan in de voorgrond is bezig het beton voor het dak van de bibliotheek te storten. In de kleine foto zijn lassers bezig met de fabricage van de ramen.



Administration Building (C)

The plasterwork to the inside and the outside of the building is finished.
Het pleisterwerk aan binnen- en buitenzijde is gereed.



Faculty Office (E) & Classroom Building (F)



The fourth and last floor of the second Classroom Building is ready and the roof is under construction.

De derde verdieping van het tweede Classroom Building is gereed en het dak is in aanbouw.



Library (K)

Concrete to the sloped roof is being cast.
Het beton van het hellende dak wordt gestort.



Staff Residence Building (H)

The concrete structure is in progress.
Het betonskelet is in aanbouw.